








| <br><b>RENAULT RVI-BERLIET<br/>MODEL</b>  | Takım conta<br>Gaskets set<br>Pochettes de joints<br>Dichtungssätze<br> | Silindir kapak contası<br>Cylinder head gaskets<br>Joint de culasse<br>Zylinderkopf<br> | Emme manifold Contası<br>Intake Manifold<br>Collect. d'admission<br>Ansaugkrümmer<br> | Egzos manifold contası<br>Exhaust manifold<br>Collect. d'echappement<br>Auspuffkrümmer<br> | Egzos boğaz contası<br>Exhaust pipe<br>Tuyau d'echappement<br>Auspuffrohr<br> | Supap kapak contası<br>Rocker cover<br>Cache-culbuteurs<br>Zylinderkopfaube<br> |
|---|--|--|--|--|--|--|
| <b>AE MAGNUM 390-420TI</b><br><b>430 - 470 - 560</b><br><b>MIDR 06.24.65 A/42</b><br><b>MIDR 06.24.65 B/42</b><br><b>MIDR 06.24.65 C/42</b><br>287-346 Kw MAGNUM<br><b>(390-471 PS) 09/96 →</b><br>12<br><b>6Cyl. 127 Ø</b> | <b>S-286 600</b><br><b>ES-286 601</b><br>50 01 834 963<br><b>CS 286 602</b><br>50 01 834 964   | <b>286 605</b><br>5001 834 870<br>613681500<br>57GC211A<br>CH54164CH<br>sand.klingerit<br>with segment<br>2x   | <b>286 613</b><br>5200 540 584<br>2x   | <b>286 714</b><br>5010 284 657<br>6x   |  | <b>286 607</b><br>50 10 284 475<br>554GB115  |




























S:Takim-Vollsatz-Full Set-Pochette Complete-Juego Complete

W:FullSet Without CylinderHead Gasket

ES:Üst Takim-Zylinderkopfsätze-Head Sets-Pochette Rodage

CS:Alt Takim-Conversionsätze-Conversion Sets-Pochettes De Complement-Juegos Uplementarios

ES+CS:S

| Karter<br>Oil pan<br>Carter d'huile<br>Ölwanne<br> | Supap lastığı<br>Valve stem<br>Queue de soupape<br>Ventilschaft<br> | Krank keçesi<br>Crankshaft<br>Vilebrequin<br>Kurbelwelle<br> | Silindir kapak sızması<br>Screw set<br>Pochette de vis<br>Schraubensatz<br> | SUITABLE TO:<br>ADAPTABLE A:<br>ADAPTABLE A:<br>PASSEND FÜR:<br>  <br><b>RENAULT RVI-BERLIET</b>  |
|---|--|---|--|--|
| <b>286 606</b><br>50 10 284 492   | <b>286 760</b><br>9x20,3/17x18<br>50 10 284 733<br>74 20 802 229<br>metallic-silicon<br>24x  | <b>286 751</b><br>150x171,6x11,5<br>50 01 834 679<br>sheet (teflon)<br><b>210 351</b><br>1 544 710<br>52,7x67,6x6,4<br>stainless              | <b>286 640</b><br>sealing ring set<br><b>286 641</b><br>137x130,4x4,5<br>6x orange color   |  2x<br>sandwich klingerit (with segment)<br>286 605<br><br>rubber<br>286 606<br><br>rubber<br>286 607<br> 2x<br>paper-sheet<br>286 613<br> 6x<br>sandwich klingerit<br>286 714<br> stainless<br>286 721<br> paper-sheet<br>286 722<br> paper<br>286 727<br> paper-sheet<br>286 723<br> paper<br>286 725<br> paper<br>286 726<br> paper<br>286 729<br> paper<br>286 623<br> 2x<br>sandwich klingerit<br>286 624<br> paper<br>286 625<br> 3X<br>paper<br>286 626<br> paper-sheet<br>286 627<br> paper<br>286 628<br> paper-silicon<br>286 629<br> paper<br>286 731 |